

Classification 11.7042 No. 8251 State *South Carolina* Place *Sumpter*




Fig. 3



Fig. 7



Fig. 8



Fig. 2




Fig. 4



Fig. 5



Fig. 6

Condition of rammed earth, buildings built 1820-1854,
on plantation of Mr. H. L. Saunders.

